Guide for Car Inspection Before Casco Insurance





In order to determine the condition of the vehicle at the moment of concluding the insurance contracts, it is necessary to take photos of the insured vehicle before concluding the insurance contract. Photos are not required if it is an extension of a previously concluded policy and the insurance cover has not been interrupted in the meantime.

Photos must be taken: from a clean car, during the day or in a well-lit room. There must be no shadows or sun reflections on the vehicle.

- Photos must be at least 1MB in size.
- Photographs must be clear and focused so that details can be seen through magnification.
- Photographs must have the date they were taken or the ability to verify metadata.
- Photographs must not be processed.

Necessary photos:

A diagonal view of the vehicle showing the front registration plate, the whole side and the front of the vehicle. The vehicle must be fully visible.






2 A diagonal view showing the rear registration plate, the whole side and the rear of the vehicle. The vehicle must be fully visible.





Photo of the vehicle windscreen. Large-scale photo of the windscreen of the vehicle as close as possible so that all sides and corners of the glass would be visible in the photo. Photo of the car's VIN code. The usual locations of the VIN code are on the windshield, on the door or under the driver's seat.







8 Photographs of the vehicle's damages. There must be a separate photograph for each lesion. Damages must be noted on the policy and approved in advance by BTA.

BTA Insurance Company does not indemnify for the costs related to the photographing of the vehicle or other additional costs that may arise during the photographing.

7 Photo (s) of accessories that are not installed in the manufacturer's factory or in an authorized workshop and with a value of more than EUR 1300 but subject to insurance. The list of accessories must be indicated on the policy and previously approved by BTA. There must be taken a separate photo of each accessory.





A photograph of the vehicle's instrument panel so

that the odometer reading is clearly legible.

5